

0221Z 02 APR 65

SECRET

DIRECTOR

25X1A

PRIORITY

25X1A

10 79950

25X1A

10210034Z 02 APR 65

OPS 1-10/04

25X1A

PRIORITY

8399

25X1A

COMMO LOGS

01156/020001Z/385

25X1A

30

1. UNK

2. WHEN SET TURNED ON TO STANDBY STEADY NOSE LIGHT CAME ON AND SHORT STEADY STROBE NOTED. SELF TEST DID NOT SEEM TO FUNCTION PROPERLY. SET TURNED OFF FOR REMAINDER OF FLIGHT. ON POST FLIGHT CHECK SELF TEST WORKED PROPERLY ALTHOUGH THE SHORT STROBE WAS PRESENT.

25X1A

1. UNK

2. NO ACTIVITY

25X1A

OPERATION SATISFACTORY EXCEPT CHANNEL 6 SHOWED G/S ACTIVITY ALTHOUGH NO SET INSTALLED. WIRING BEING CHECKED. RADIO AND NAVAIDS OPERATION SATISFACTORY.

END OF MSG